



Soak a clean and dry lint-free cloth with PK 700 or PK 900. Clean small areas of approx. 0.5 m² of the surface to be painted and wipe these areas immediately afterwards with a dry cloth of the same quality. PK 700 and PK 900 should not dry on the surface being treated.

Attention:

Individual paint coats may suffer surface etching from the use of PK 700 or PK 900. In this case, ensure a good flash-off of the substrate before going on with the repair so that no solvents will be trapped in the new paint system. In extreme cases, remove the affected paint coats before applying the new paint system.

Finishing

As specified in the R-M refinishing processes.

Safety instructions

PK 700: 2004/42/IIIB(al)(850)840: The EU limit value for this product (product category: IIB.al) in ready-for-use form is max 850 grams of VOC per liter. The VOC content of this product is 840 g/l.

PK 900: 2004/42/IIIB(al)(850)840: The EU limit value for this product (product category: IIB.al) in ready-for-use form is max 850 grams of VOC per liter. The VOC content of this product is 840 g/l.

It cannot be ruled out that this product contains particles < 0.1 µm.

The products are suitable for professional use only.

For the use of these products please adhere to the actual safety recommendations and the personal protective equipment.

Завършване

Продължете със следващата стъпка от репаратурния процес.

Инструкции за безопасност

PK 1000: 2004/42/IIIB(al)(200)186: готов за употреба макс. 186 грама ЛОС на литър.

PK 2000: 2004/42/IIIB(al)(200)198: готов за употреба макс. 198 грама ЛОС на литър.

Възможно е този продукт да съдържа частици < 0.1 µm.

Само за професионална употреба.

Моля, спазвайте препоръките за безопасност и носете защитно облекло.